

OCE006 - Anticipate Spare parts shortage

Kit to replace Gearboxes WA47 with KA39 on inlet dosing belt two way


Value and benefit

- Safer solution with newer component available in the market.
- Can prevent long downtimes in case of failure
- SEW gearboxes WA47 are phased out by manufacturer.
- Spare Part unavailability.
- Risk of long Downtime for equipment at Bottlers prod plants as it takes an upgrade to be able to install active newer components.

Description

- New system with gearboxes SEW KA39:
 - The new system consists of gearboxes KA39 with similar reduction ratio, replacing the obsolete ones.
 - Available in case of brushless and asynchronous motors (Motors can be recovered only if brushless)
 - It includes adaptation kit

Kit Brushless



Kit asynchronous

