

## KEY FIGURES

## Budget price:

20 K euro installation included

## Payback estimation:

Prevent long downtimes in case of failure

## Installation time:

3 Days

## Machine downtime:

Less than 1 Day

## Average delivery time:

10 weeks

## Can be combined with:

- OCE010 - 011 - 012 HMI Obsolete

## Machine application:

- All EOL machines with motion control

## Targeted sub assembly:

- Control cabinet

# Obsolete ELAU controller LMC600 and LMC400 Replacement

Obsolescence

## O&U ID: OCE014

### BENEFITS


- Safer solution with newer component LMC402/802 available in the market.
- Spare Part availability.
- Prevent risk of long Downtime for equipment at Bottlers prod plants as it takes an upgrade to be able to install active newer components.

### DESCRIPTION

- The upgrade consists of replacing the controller and updating the drive firmware and development environment.

### DELIVERABLES

- Spare Part availability
- Prevent claim due to long downtimes in case of failure
- Latest-generation processors
- 1GB memory
- Ethernet communication port up to 1 Gbps



All following Sidel parts code controller can be replaced by OCE014:

00000195346: Pac Drive 3 Controller LMC400  
00000167646: Pac Drive 3 Controller LMC600